## COOLING/HEAT PUMPS

	A STATE OF THE PARTY OF THE PAR	All a	DESCRIPTION NONE	I LOCAL SERVICE	5 - P -			i Constitution of	
1.0	Air Conditioning:	3.0	Cooling Capacity:	19.0 Hous	e Fan	П			
1.0	1.1 Air Cooled	0.0	36 //_ x 1,000 BTU/hr	2710 22040					
	☐ 1.2 Water Cooled			20.0 Evap	orativ	e Coole	r: 🗆		
		4.0	Failure Probability:	Moto					
	☐ 1.4 Gas Chiller		High		ne Spe	ed			
			☐ Medium		wo Spe				
2.0	Heat Pump:		Low			Conditi	on:		
	2.1 Air Source								
						nper Location:			
	2.3 Ground/Water Source 20//yrs old								
	2.4 Independent Unit								
14-10-1	IMPROVEME	ENT	RECOMMENDATIONS NONE	AT PRES	ENT	A TELL			
		There	☐ Incomplete ☐ Not Found						
	Data Plate: Missing Not Legi	IIDIE rative	☐ Incomplete ☐ Not Found ☐ Restricted Access ☐ Outdoor Coil Covered						
Reference	Outdoor Temperature Prevented Testing in: Cooling Mode Heating Mode					=			
ren	✓ Heat Gain and Heat Loss Calculations Not Done ☐ House Fan Not Tested ☑ Window A/C Excluded					÷	0		
efe	Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern:								
B	Asbestos may be present in many building	g prod	lucts and materials. Environmental Consultants can assist if this	s a concern.	ĭ		F		
1.0	AIR CONDITIONING - undersized?	?, ol	d, service						
2.0	HEAT PUMP - undersized?, old, serv								
2.3	Ground/Water Source - buried pipin	ig, si	apply well, discharge well, suspect						
5.0	Compressor - old, inoperative, noisy								
6.0	Plenum / Indoor Coil - dirty, corrode	ed, fi	ost{temperature drop} too great, too small						
			Good /						
7.0	Outdoor Coil - dirty, iced up, not leve	el, fi	n damage						
8.0	Water Cooled Coil - leak								
9.0	Outdoor Fan - noisy, inoperative, dan								
10.0	Condensate Tray / Line / Pump - lea	ak, s	tains, blocked, inoperative, trap				-		
					_		-		
11.0			on insulation missing seal at plenum/wall		R	R	0	D	
12.0	Indoor Fan - dirty, noisy, undersized?	7, VI	bration, adjustment						
12.0	D. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	d ol	atmosted distrement comment		-		-		
13.0	Ductwork - undersized?, disconnected, obstructed, dirty, rust, support, incomplete, humidifier damper, balancing, damaged								
	meompiete, numumer damper, odianemg, damaged								
14.0	Attic Ductwork Insulation - damage, incomplete								
14.0	Attic Ductwork Histiation - damage,	, me	ompiece						
15.0	Supplemental Cooling - if necessary								
16.0	Attic Drip Pan - leaking, missing, cor	mmo	on drain						
	- drain line - missing,								
17.0	Water Lines - supplied from pool, lea								
18.0	Thermostat - damaged, location, adju								
19.0	HOUSE FAN - old, inoperative, vent	outs	ide, wiring						
20.0	EVAPORATIVE COOLER - motor	r, co	nnection, wiring, pump						
			es, clips, bleeder, water line, air gap						
	- fan, tray, housing, roof jack, damper								
	- old, lea	ak, l	oose, inoperative, rust			and the same of			
COMMENTS									
See	Supplementary Section	prop	riate Materials or Installation		_				
Commit	Temp: 54,5°//	Po	turn Temp: 72.6°/ \ \ \ \	r: 18.1°	1	Ť.			
MIDDIN	LCHID. JP. J	PC	Luin 10mp. (9.10)					_	

The Home Reference Book ©