

PLUMBING

DESCRIPTION

1.1.1 Service Piping into House:

- Lead Copper
 Plastic
 Galvanized Steel
 Not Visible

1.4 Supply Piping in House:

- Galvanized Steel Plastic
 Copper Brass
 Not Visible

Main Shut Off Valve at Front basement wall

1.4.1 Water Flow (Pressure): Functional

- Above Average Below Average
 Typical for Neighborhood 75 PSI

1.6 Water Heater:

- Combination System (see Heating 18.0)
 Conventional Induced Draft Tankless/Indirect
 Electric Gas Oil _____
 Estimated Age: 8 / _____ yrs
 Failure Probability high med. low
 Tank Capacity 73 / _____ gallons

1.7 Hot Water Circulating System

2.3 Waste Piping in House:

- Galvanized Steel Cast Iron
 Plastic Lead
 Copper Not Visible

2.7 Solid Waste Pump

2.8 Sump Pump

2.9 Laundry Tub Pump

IMPROVEMENT RECOMMENDATIONS NONE AT PRESENT

Reference	Limitations	Task	Location	Time
	<input type="checkbox"/> Water Shut Off/Winterized <input type="checkbox"/> Main Valve Not Located <input type="checkbox"/> Gas Shut Off <input type="checkbox"/> Septic System Not Inspected Fixtures Not Tested/Not in Service: <input type="checkbox"/> Water Heater <input type="checkbox"/> Toilet <input type="checkbox"/> Sink <input type="checkbox"/> Basin <input type="checkbox"/> Bathtub <input checked="" type="checkbox"/> Hot Tub <input checked="" type="checkbox"/> Tub/Sink Overflows Not Tested <input type="checkbox"/> Whirlpool Bath <input type="checkbox"/> Sauna <input type="checkbox"/> Shower <input type="checkbox"/> Bidet <input type="checkbox"/> Laundry Tub <input checked="" type="checkbox"/> Water Treatment Equipment Not Inspected <input type="checkbox"/> Restricted/No Access to: _____ <input checked="" type="checkbox"/> Concealed Plumbing Not Inspected <input checked="" type="checkbox"/> Isolating/Relief Valves & Main Shut-Off Valve Not Tested <input checked="" type="checkbox"/> Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern. <input checked="" type="checkbox"/> Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.			
1.1	SUPPLY- Public - piping to house, leak, pressure regulator, pressure/flow, lead			
1.2	Private - pump, tank - leak, waterlogged, rust, relief valve			
1.3/5	Main Shut Off Valve / Isolating Valve - leak, damaged, handle, meter			
1.4	Piping - leaks, freezing, noise, rust, cross connections, support, pressure/flow - steel, lead, polybutylene			
1.6	Water Heater - wiring, combustion air, controls, valve, leak, drip pan, old - Tank - rust, leak, soot, relief valve, discharge tube - reduced, extend, location - Exhaust Flue / Damper / Draft Hood - slope, rust, connections, size, support - location, clearance from combustibles, exhaust gases, aluminum			
1.7	Circulating System - inoperative, pump			
4.0	Gas Piping - leaks, material, support, rust, bonding, installation			
2.1/2	WASTE - Public / Private - odor, backup, clean out, unsealed openings, video scan			
2.3	Piping - leaks, slope, freezing, obstructions, replace lead/steel when renovating, rust, support			
2.4/5	Trap/Tail Piece/Floor Drain - leak, prime, dry, S-trap, corroded, not visible			
2.6	Venting - auto-vent, too short/tall, frost, suspect, siphon, diameter			
2.7/9	Solid Waste Pump / Laundry Tub Pump - inoperative, leak			
2.8	Sump Pump - inoperative, leak, backflow valve, clogged, lid, discharge, not visible			
3.1/2	FIXTURES - Sink / Basin - leak, cracked, rust, chipped, slow drain, airgap, eventual updating likely - Sink / Basin - leak, cracked, rust, chipped, slow drain, airgap			
3.3	Faucet - leak, inoperative, loose, stiff, drip, handle, diverter, vegetable sprayer Faucet - leak, inoperative, loose, stiff, drip, handle, shower head, diverter			
3.13	Outdoor Faucet - leak, damage, shut off, loose			
3.4	Toilet - leak, inoperative, loose, running, slow flush, cracked, floor damage, mechanism Toilet - leak, inoperative, loose, running, slow flush, cracked, floor damage, mechanism			
3.5/6	Bathtub / Bathtub Enclosure - leak, tile, caulk, grout, window, damage, rust, <u>drain slow</u> , doors Bathtub / Bathtub Enclosure - leak, tile, caulk, grout, window, damage, rust, drain slow, doors	R	Bath	O D
3.7	Shower Stall - leak, tile, caulk, grout, loose, door, possible concealed damage Shower Stall - leak, tile, caulk, grout, loose, door, possible concealed damage			
3.8	Whirlpool Bath - hand held shower, GFCI, pump, leak, settlement, noisy, motor-access, switch			
3.9/10	Bidet - leak, cracked, loose / Sauna - inoperative			
3.11/12	Bathroom / Kitchen Fan - inoperative, discharge outside, noisy, desirable, ductwork			
3.14	Laundry Tub - leak, damage, cracked, concrete, loose, slow drain			

hole at chimney entry } R B O D

COMMENTS

- See Supplementary Section Inappropriate Materials or Installation